

LONGS PEAK RESOURCES, LLC

July 13, 2018

VIA FedEx

Director
Air and Toxics Technical Enforcement Program
Office of Enforcement, Compliance and Environmental Justice
U.S. EPA Region VIII
Mail Code 8ENF-AT
1595 Wynkoop Street
Denver, CO 80202-1129

RE: Initial Annual Report - NSPS OOOOa Facility
Weld County, CO

Dear Director:

In accordance with 40 CFR Part 60.5420a(b), Longs Peak Resources, LLC (Longs Peak) is submitting the initial annual report for ~~storage vessel and~~ collection of fugitive emission components at a well site affected facilities under NSPS OOOOa. CEDRI was unavailable for submittal due to no "physical address" for the site, therefore the report is being submitted in hard copy.

Company Name, Facility and Address [§60.5420a(b)(1)(i)]:

Longs Peak Resources, LLC

Pismo 35-2-2-2CH (API#05-123-40723)

(b) (9)

NWNE Section 35, T12N, R66W approximately 2.2 miles south of the Wyoming border and 9.3 miles east of I25

Affected Facility [§60.5420a(b)(1)(ii)]:

Collection of Fugitive Emission Components Affected Facility – Pismo 35-2-2-2CH

Report Period [§60.5420a(b)(1)(iii)]:

May 16, 2017 – May 15, 2018

Certification [§60.5420a(b)(1)(iv)]:

I certify based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.

10701 MELODY DRIVE, SUITE 515
NORTHGLENN, CO 80234
303.997.5558

LONGS PEAK RESOURCES, LLC

Semi-annual Surveys [§60.5420a(b)(7)]:

July 14, 2017 (time began and ended not recorded)
Forrest Thorniley: 4+ years OGI camera operation for O&G site LDAR
Weather: Sunny wind from the south approximately 11 mph and 76°F
OGI survey and resurvey: FLIR GasFindIR camera
No deviations from monitoring plan
Leaks: 2 PRVs, 1 valve, and 3 connectors
All leaks repaired as required
No difficult or unsafe to monitor components
All leaks repaired by 7/28/2017 (remonitor date)
No delay of repair components

January 30, 2018 (time began and ended not recorded)
Asher Weinberg: 2+ years OGI camera operation for O&G site LDAR
Weather: Partly cloudy wind from the west approximately 17 mph and 47°F
OGI survey and resurvey: FLIR GasFindIR camera
No deviations from monitoring plan
Leaks: No leaks detected
No difficult or unsafe to monitor components
No delay of repair components

Please feel free to contact Ashley Campsie with Evergreen Environmental Engineering at ashley.campsie@eeeng.net or at 303-670-3480 with any questions regarding this report.

Sincerely,

Longs Peak Resources, LLC

(b) (6)

David Clarkson
COO

Enclosures